


Diagram 17 illustrates the process of attaching the backrest to the desk frame. The backrest (17) is shown being aligned with the frame (16). Arrows indicate the insertion of screws (15) into the pre-drilled holes in the backrest and frame to secure the connection. A separate piece (14) is shown above the frame, likely a top panel or another component to be attached later.

This diagram shows the exploded perspective view of the cabinet assembly. It includes the main cabinet body (10), two side panels (11 and 12), and a detailed view of the corner bracket (G) and screws (K) used for assembly.

step7



22RKH001
(300x600x1050)

step5

This diagram illustrates the fifth step of the assembly process. It shows the desk frame with the front and right side panels partially attached. A circular callout, labeled '13', provides a detailed view of the connection point where a metal bracket is being secured to the side panel using screws. A separate circular inset at the bottom right, labeled 'I', shows a close-up of the metal bracket and its mounting hardware.

①	350*90*12	2
②	385*135*16	1
③	355*327*5	1
④	316*70*12	1
⑤	720*537*16	1
⑥	898*557*43	1
⑦	366*536*16	1
⑧	366*536*16	1
⑨	366*60*16	1
⑩	1512*555*25	1
⑪	1600*900*43	1
⑫	898*557*43	1
⑬	521*385*16	1
⑭	1200*240*43	1
⑮	954*107*16	1
⑯	900*155*16	1
⑰	1007*236*43	1

Finish

I			A	 15A	
J			B	 15A	
K	 3*12		C		
L	 4*14		D	 12A	
M	 4*20		E	 12A	
N	 3*30		F		
O	 5*10		G		
P			H		