





# CHEST OF DRAWERS

MODEL:COD-PURI-6D-WHWD



## ASSEMBLY INSTRUCTIONS

Please read instructions carefully before assembly.




Two persons and tools required for assembly





## HARDWARE

A	x38	B	x14	C	x18	D	x46	E	x12	F	x2
7x35mm		15x12mm		Ø6x30mm		M4x40mm					
G	x6	H	x36	I	x2	J	x26	K	x12	L	x12
		M3x12mm		M4x30mm						M3x14mm	
M	x12	N	x6	O	x2	P	x24	Q	x4	R	x2
M4x10mm		Ø6x50mm				12x10mm				M4x14mm	


## PARTS

Wipe with dry cloths









3




O	x2	R	x2	A	x8
		M4x14mm		7x35mm	

5





B	x2
15x12mm	

4




C	x12	N	x6
Ø6x30mm		Ø6x50mm	


6




D	x8	E	x6
M4x40mm			



7




D	x2
	
M4x40mm	



9




C	x6	G	x6
			
Ø6x30mm			


8







D	x6	E	x6
			
M4x40mm			

10











B	x6
	
15x12mm	

# 11




Q	x4	J	x26

# 13






x6

# 12



Pre-drill hole in wall



F	x2	I	x2
		M4x30mm	

B	x6	P	x24	A	x30	D	x30	L	x12
15x12mm		12x10mm		7x35mm		M4x40mm		M3x14mm	

