


















Ax12  $\varnothing 6 \times 34 \text{mm}$	Bx12  $\varnothing 15 \times 9 \text{mm}$	Cx14  $\varnothing 8 \times 30 \text{mm}$	Dx4  $\varnothing 4.0 \times 25 \text{mm}$	Ex27  $\varnothing 3.5 \times 14 \text{mm}$
Fx3 	Gx10  $\varnothing 7 \times 50 \text{mm}$	Hx2 	Ix2 	Jx2 
Kx12  $\varnothing 21 \text{mm}$	Lx1  M4			

1




2



3

Ax8





Cx4






Bx8



Kx8





7





7

4



5




6

Dx4



Hx2




7

Ex15




Jx2



8

1x2



9

