


IHOMDEC
Assembly Instruction
Parent-Child Hall Tree
IHD-HT04-FB



Customer Service Before Return

If part is missing or damaged, or you need help with assembly, please do not hesitate to contact us.

SELLER CONTACT INFORMATION:
contacts@ihomdec.com
IHD23-HY-11



















Before Assembly








IMPORTANT NOTE:


- Make sure all parts and hardware are included and free of obvious Defect before disposing of any packaging
- Place all wooden parts on a clean and smooth surface such as a rug or carpet to avoid the parts from being scratched.
- DO NOT tighten all screws and bolts until completely assembled.
- Assembly will require two people.

PART LIST

1 	2 	3 	4 	5 	6 	7 	8 
1pc	1pc	1pc	1pc	1pc	1pc	1pc	2pcs
9 	10 	11 	12 	13 	14 	15 	16 
2pcs	1pc	1pc	2pcs	1pc	3pcs	2pcs	1pc

HARDWARE LIST


A  M6x12mm	B  M6x25mm	C  M6x40mm	D 	E 	F 	G 
16pcs	8pcs	20pcs	14pcs	7pcs	8pcs	1pc



NOTED:


1. Do not fully tighten all bolts until all parts are in place. Failure to follow these instructions may cause the bolt to misalign during assembly.
2. To prevent injury and property damaged from unexpected tipping of furniture, we highly recommend installation of the anti-tip kit included with this product.

Step1




C x 8PCS

Step2



C x 6PCS

Step3




C x 6PCS

NOTED:

1. Do not fully tighten all bolts until all parts are in place. Failure to follow these instructions may cause the bolt to misalign during assembly.


2. To prevent injury and property damaged from unexpected tipping of furniture, we highly recommend installation of the anti-tip kit included with this product.

Step4



B x8PCS


Step5



A x 10PCS


1. Do not fully tighten all bolts until all parts are in place. Failure to follow these instructions may cause the bolt to misalign during assembly.
2. To prevent injury and property damaged from unexpected tipping of furniture, we highly recommend installation of the anti-tip kit included with this product.

Step 6




E x 7PCS
D x 14PCS

Step 7



F x 8PCS

Step 8



A x 6PCS