





# CHEST OF DRAWERS

MODEL:COD-HAMP-3D-WH




















## ASSEMBLY INSTRUCTIONS

Please read instructions carefully before assembly.





Two persons and  
tools required for  
assembly

### HARDWARE



A	x19	B	x7	C	x4	D	x27	E	x12	F	x1
											
7x35mm		15x12mm		Ø6x30mm		M4x40mm				M4x30mm	
G	x1	H	x1	I	x1	J	x12	K	x6	L	x18
											
M4x14mm						M3x14mm				M3x12mm	
M	x12	N	x6	O	x6	P	x12	Q	x4		
											
M4x10mm						12x10mm					

## PARTS

Wipe with dry cloths




1




K	x6	L	x18
M3x12mm			

2




I	x1	G	x1	A	x4
		M4x14mm		7x35mm	

3





D	x12	E	x12
M4x40mm			

4







6





Q	x4

5




C	x4	B	x4
Ø6x30mm		15x12mm	

7



J	x6
M3x14mm	

Pre-drilled hole at wall



10











⑩ x3



M4x10mm

x3

B	x3	P	x12	A	x15	D	x15	J	x6	M	x6	N	x6	O	x6
															
15x12mm		12x10mm		7x35mm		M4x40mm		M3x14mm		M4x10mm					