





BAR TABLE

MODEL:BS-TAB-CARR-WHWD





ASSEMBLY INSTRUCTIONS

Please read instructions carefully before assembly.




Two persons and tools required for assembly

HARDWARE


A	x14	B	x14	C	x16	D	x14	E	x32	F	x36
											
7x35mm		15x12mm		Ø6x30mm		M4x40mm		M4x25mm			
G	x11	H	x8								
											
M3x14mm											

PARTS


Wipe with dry cloths




1




3




2



4




5






G	x11
	
M3x14mm	


7



B	x6	F	x6
			
15x12mm			




6




A	x6	C	x4
			
7x35mm		Ø6x30mm	

8




D	x2
	
M4x40mm	

9




E	x16
 M4x25mm	

11




10




E	x8
 M4x25mm	

12




C	x6	E	x8
 Ø6x30mm		 M4x25mm	


13



15



14



16

Assembly
completed

