


PARTS LIST

1. DRESS RING
2. SPOUT
3. GRUB SCREW M5X4
4. AERATOR 5 L/M
5. O-RING 12X2.0
6. O-RING 49X3.0
7. O-RING 12X2.0



MAINTENANCE AND CARE:

- All surfaces should be cleaned with mild liquid detergent or soap and water.
- Do not use cream cleaners or citrus based cleaning products, as they are abrasive.
- Use of unsuitable cleaning agents may damage the surface. Any damage caused in this way will not be covered by warranty.