



Ax66




Bx66



Cx66




Dx24



Ex72




Fx24



1


Refer to the diagram to install A,B and C screws in their designated position.



X4

2


Refer to the diagram to install A,B and C screws in their designated position.



X4

3


Refer to the diagram to install A,B and C screws in their designated position.



X2

4


Refer to the diagram to install A,B and C screws in their designated position.



X2

5


Assemble the parts in the manner shown. Use C and D screws to secure the connections.




x 2

6

As shown in the picture, install the chair legs at the four corners of the rectangular frame, and then fix the connection points with screws E.




x 4



x 2

7


Place A,C screws in the designated position and align them with the pre-drilled holes. Then use B screws to fasten the connection.




x 2

8

Assemble the parts in the manner shown. Use C and D screws to secure the connections.




9



As shown in the picture, install the table legs at the four corners of the rectangular frame, and then fix the connection points with screws E.

x 4



10

Place A,C screws in the designated position and align them with the pre-drilled holes. Then use B screws to fasten the connection.

