


Two-person Assembly

## TOOLS



## HARDWARE




Ax49  
M6x15



Bx3




Cx1  
18\*6\*1.5




Dx2  
M5x12


# PARTS




1X1




2X2



3X1



4X1



5X1



6X2




7X1



8X1




9X2



10X2




11X1




12X1




13X1



14X1





15X1






16X1








17X1



































17

