











WINDSOR

WN01

DO NOT USE DRILL, USE ALAN KEY PROVIDED



A		1
B		1
C		1
D		4
E		4
F		4
G		1