


IHOMDEC
Assembly Instruction
BAR TABLE SET



Customer Service Before Return

If part is missing or damaged, or you need help with assembly, please do not hesitate to contact us.

SELLER CONTACT INFORMATION:
contacts@ihomdec.com










Before Assembly


IMPORTANT NOTE:


- Make sure all parts and hardware are included and free of obvious Defect before disposing of any packaging.
- Place all wooden parts on a clean and smooth surface such as a rug or carpet to avoid the parts from being scratched.
- DO NOT tighten all screws and bolts until completely assembled.
- Assembly will require two people.

PART LIST

PART LIST			
1	2	3	4
			
1 PC	2 PCS	1 PC	2 PCS
5	6	7	8
			
4 PCS	8 PCS	4 PCS	8 PCS

HARDWARE LIST


A	B	C	D	E	F
					
M6X12mm	M6X30mm	M6X40mm	M6X45mm	M6X55mm	
19 PCS	4 PCS	4 PCS	16 PCS	16 PCS	1 PC



NOTED:


Do not fully tighten all bolts until all parts are in place. Failure to follow these instructions may cause the bolt to misalign during assembly.

Step 1




B X 4 PCS

Step 2




A X 3 PCS

Step 3



C X 4 PCS

Step 4




X 4

A X 16 PCS

C X 16 PCS

Step 5



X 4

E X 4 PCS

Step 6

