





CHEST OF DRAWERS

MODEL:COD-PURI-5D-WHWD



















Two persons and tools required for assembly

ASSEMBLY INSTRUCTIONS



Please read instructions carefully before assembly.

HARDWARE


A	x30	B	x10	C	x20	D	x45	E	x20	F	x2
											
7x35mm		15x12mm		Ø6x30mm		M4x40mm				M4x30mm	
G	x2	H	x2	I	x2	J	x14	K	x10	L	x30
											
M4x14mm						M3x14mm				M3x12mm	
M	x10	N	x4	O	x18	P	x20				
											
M4x10mm						12x10mm					

PARTS

Wipe with dry cloths




1




a.1





a.2




a.3



K	x8	L	x24
			
M3x12mm			


2




a.1





a.2




a.3




K	x2	L	x6
			
M3x12mm			


3




A	x7
 7x35mm	


5







D	x2
 M4x40mm	


4




C	x16
 Ø6x30mm	

6




B	x1
 15x12mm	


7




9







8



10






11



B	x6
 15x12mm	







12







O	x18






13

Pre-drilled hole at wall



G	x2	H	x2	I	x2	F	x2
 M4x14mm						 M4x30mm	






14



x3

B	x3	P	x12	A	x15	D	x15	J	x6
15x12mm		12x10mm		7x35mm		M4x40mm		M3x14mm	



15




x2

P	x8	A	x8	D	x8	J	x8
12x10mm		7x35mm		M4x40mm		M3x14mm	



16



Screw from the inside of the drawers



17



Screw from the inside of the drawers

