


CHEST OF DRAWS

MODEL:COD-A7-3D-WD



ASSEMBLY INSTRUCTIONS

Please read instructions carefully before assembly.



Two persons and tools required for assembly

HARDWARE

	Α	x13	В	x7	С	x18	D	x33	Е	x18	F	x6
	©27 J						Allenting		Ø _{ZZZZ}		NI SE	
	7x <u>35mm</u>		15×12mm		Ø6x30mm		M4x40mm		M3x12mm			
	G	x6	Н	х4	ı	x1	J	x8	K	x4	L	x2
	M4x10mm								-			
Ī	М	x18	N	x2	0	x8	Р	x6	Q	x8	R	х3
			M4x14mm		M6x60mm		12x10mm					
Ī	S	x6	Т	x16	U	x2	٧	x18	W	x2		
	Omm		AIIIII A		600				Annual Company			
	M4x18mm		M4x25mm				M3x14mm M4x30mm					

