ASSEMBLY INSTRUCTIONS

PAGE: 1/5

MODEL: JESSIE 1.8M IV UNII


Before you begin, please follow assembly instructions carefully, then follow them step by step.

Read instruction carefully . See Furniture Parts list and Hardware List for guidance . Be sure you have all parts before you start assembling . Place and assemble furniture on a clean flat soft surface , such as carpet or rug to pervent being scratched .

	PART LIST	QTY
1	TOP PANEL	1 PC
2	BOTTOM PANEL	1 PC
3	SIDE PANEL (L)	1 PC
4	SIDE PANEL (R)	1 PC
5	CENTER PANEL	2 PCS
6	BONE PANEL	1 PC
7	BACK PANEL	1 PC
8	DRAWER FRONT (1)	1 PC
9	DRAWER FRONT (2)	1 PC
10	DRAWER FRONT (3)	1 PC
11	DRAWER BACK	3 PCS
12	DRAWER SIDE	6 PCS
13	DRAWER BOTTOM	3 PCS
14	APRON FRONT	1 PC
15	APRON BACK	1 PC
16	APRON SIDE	2 PCS
17	CENTER LEG	1 PC

SELF-PREPARED TOOLS: Tools below are NOT included in package.				
SCREWDRIVER	HAMMER			

HARDWARE				
Α	MINI FIX A1 A2 44 A3 A3	12 SETS		
В	M8 X 30MM WOOD DOWEL	24 PCS		
С	M6 X 50MM CSK CAP WOOD SCREW	8 PCS		
D	ALLEN KEY M4	■ 1 PC		
Е	M3.5 X 16MM C.B SCREW ⊕	- 36 PCS		
F	M4 X 30MM C.B SCREW	· 2 PCS		
G	M4 X 38MM C.B SCREW	- 38 PCS		
Н	5/8 NAIL 0	60 PCS		
I	5/8 PVC NAIL LEG	5 PCS		
J	14" DRAWER SLIDE J2 (L)	(R) 3 SETS		



10



Please ensure that all surfaces and edges with colours/laminations are facing forward/outward.



PAGE: 2/5

SCREWDRIVER REQUIRED

SCREWDRIVER


REQUIRED

MODEL: JESSIE I.OM IV UNII

STEP 1

- Insert hardware **A2** onto panel **(1)**, **(14)** and **(15)**. (Repeat 12 times.)


- Insert hardware **B** onto panel **(14)** and **(15)**. (Repeat 4 times.)



STEP 2

Insert hardware A1 onto panel (16).
(Repeat 4 times.)

Insert hardware B onto panel (6).
(Repeat 4 times.)




SCREWDRIVER REQUIRED

* Ensure the arrows on hardware A1 point towards mounting positions.

STEP 3

- Insert hardware A1 onto panel (3), (4) and (5). (Repeat 8 times.)

- Insert hardware **B** onto panel **(3)**, **(4)** and **(5)**. (Repeat 16 times.)



* Ensure the arrows on hardware A1 point towards mounting positions.

STEP 4

