


1

- Apply Teflon Tape to Threaded Elbow.
- Firmly screw the Outlet onto Threaded Elbow.



recommended working pressure  
**150-500 KPa**  
maximum hot water temperature  
**75 degrees**