



1

Apply Teflon Tape to Threaded Elbow.

Screw Spout Adapter onto Threaded Elbow by hand and tighten firmly using Allen Key



2





maximum hot water temperature 75 degrees