




1

- Apply Teflon Tape to Threaded Elbow.
- Firmly screw the Shower Arm onto the Threaded Elbow.



recommended
working pressure

**150-500
KPa**



maximum hot
water temperature

**75
degrees**