




1

- Apply Teflon Tape to Threaded Elbow.
- Fit Dress Plate over Threaded Elbow.
- Firmly screw on the Shower Arm.



 recommended working pressure
150-500 KPa

 maximum hot water temperature
75 degrees