
PARTS LIST

- I. DRESS PLATE
- 2. AERATOR
- 3. O-RING 43X2.5MM
- 4. O-RING 1 1X2.0MM
- 5. GRUB SCREW M5X5
- 6. SPOUT



MAINTENANCE AND CARE:

- All surfaces should be cleaned with mild liquid detergent or soap and water.
- Do not use cream cleaners or citrus based cleaning products, as they are abrasive.
- Use of unsuitable cleaning agents may damage the surface.
 Any damage caused in this way will not be covered by warranty.